




## RIVER MILE 10.9 REMOVAL ACTION CAPPING OPERATIONS WEEKLY STATUS REPORT

### Summary of capping operations through week ending March 23, 2014


The placement of the fabric and armoring stone continued this week. As of March 23 an estimated 28% of the dredged and capped area has been protected with this armoring layer. Current projections have all work being completed in early May, 2014. The attached figure shows the section of RM 10.9 where the fabric and stone has been placed.

*All capping operations were conducted within acceptable water quality monitoring limits. Hardware and software issues were uncovered that impacted the variability of the recorded turbidity data. The variable turbidity data does not appear to be related to the placement of stone during capping operations.*

### Capping Progress to Date Shown in Blue



## Real-Time Water Quality Monitoring





Water Quality Monitoring Locations